DIN EN 993-10:2020-12 (E)

Methods of test for dense shaped refractory products - Part 10: Determination of permanent change in dimensions on heating

Contents

Page

European foreword 3

1 Scope 5

2 Normative references 5

3 Terms and definitions 5

4 Principle 6

5 Apparatus 6

6 Test pieces 7

7 Procedure 7
7.1 Drying of the test pieces 7
7.2 Measurement of test pieces 7
7.2.1 Linear measurement by dial gauge apparatus (Method 1) 7
7.2.2 Linear measurement by Vernier callipers (Method 2) 7
7.2.3 Volume measurement (Method 3) 8
7.3 Mounting of test pieces in the furnace 8
7.4 Test temperature 8
7.5 Temperature measurement and distribution 8
7.6 Heating 8
7.7 Maintenance of test temperature 9
7.8 Sampling of furnace atmosphere 9
7.9 Cooling 9
7.10 Measurement of test pieces after firing 9
7.10.1 Linear measurement (Methods 1 and 2) 9
7.10.2 Volume measurement (Method 3) 9

8 Expression of results 10

9 Test report 10

10 Precision and bias 11
10.1 Interlaboratory study 11
10.2 Precision data 11
10.2.1 Repeatability 11
10.2.2 Reproducibilty 11
10.2.3 Bias 11

Table 1 -- Permanent change of dimensions on heating 11

Figure 1 -- Length-measuring device (method 1) (side view) 12

Figure 2 -- Test piece carrier (method 1) - (plan view) 13

Figure 3 -- Measuring points when using Vernier callipers (method 2) 13