ISO 3613:2021 (E)

Metallic and other inorganic coatings — Chromate conversion coatings on zinc, cadmium, aluminium-zinc alloys and zinc-aluminium alloys — Test methods

Contents

Foreword

Introduction

1 Scope

2 Normative references

3 Terms and definitions

4 Reagents

5 Apparatus

6 Test methods

- 6.1 General
- 6.2 Test for the presence of a colourless chromate coating on zinc
- 6.3 Test for the presence of a colourless chromate coating on zinc and cadmium
- 6.4 Test for the presence of a colourless chromate coating on zinc-aluminium (mass fraction of aluminium: 5 %) alloys
- 6.5 Test for the presence of hexavalent chromium in both colourless and coloured chromate coatings
- 6.5.1 General
- 6.5.2 Test method employing test solution C 1
- 6.5.3 Test method employing alternative test solution C 2 (destructive)
- 6.5.4 Expression of results
- 6.5.5 Calibration of spectrophotometer
- 6.6 Determination of hexavalent chromium content of coloured chromate coatings
- 6.6.1 Preparation of calibration graph
- 6.6.2 Blank test
- 6.6.3 Determination
- 6.6.4 Expression of results
- 6.7 Determination of total chromium content of coloured chromate coatings
- 6.7.1 Preparation of calibration graph
- 6.7.2 Blank test
- 6.7.3 Determination
- 6.7.4 Expression of results
- 6.8 Determination of mass per unit area of both colourless and coloured chromate coatings by gravimetric method
- 6.9 Test for adhesion by abrasion
- 6.10 Quality evaluation test of chromate layers on zinc and cadmium surfaces

7 Test report

Page count: 11