ISO 10111:2000-06 (E)

Metallic and other inorganic coatings - Measurement of mass per unit area - Review of gravimetric and chemical analysi s methods

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 2

3 Terms and definitions 2

4 Principle 3

5 Special equipment 3

6 Preparation of test specimen 3

7 Measurement of coated area 4

8 Determination of mass of coating by chemical analysis 4

9 Gravimetric determination of mass of coating 5

10 Calculations 6

Annex A (normative) Reagents for selective dissolution of metal layers 7

Bibliography 13