ISO 5722:2023-03 (E)

Fine ceramics (advanced ceramics, advanced technical ceramics) - Test method for determining tensile and shear creep of ceramic adhesive

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Principle 2

5 Apparatus 2

6 Test specimen 3
6.1 Test specimen size and preparation 3
6.2 Test specimen storage 6

7 Test procedures 6
7.1 Measurement of specimen dimensions 6
7.2 Measurements of the tensile or shear creep 6
7.3 Measurements of the cross-bonded area and thickness 9
7.4 Loading procedure 9
7.5 Recording of displacement and rupture time 9

8 Calculation of results 9
8.1 Calculation of the tensile creep 9
8.2 Calculation of the shear creep 9

9 Test report 10

Bibliography 11