ISO 9271:2023-02 (E)

Decontamination of radioactively contaminated surfaces - Testing of decontamination agents for textiles

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms,definitionsandsymbols 1
3.1 Terms and definitions 2
3.2 Symbols 3

4 Principle 3

5 Apparatus 4
5.1 Beakers 4
5.2 Radiation detector 4
5.3 Pipettes 5
5.4 Two polytetrafluoroethylene (PTFE) or quartz ampoules 5
5.5 Thermostat 5
5.6 Storage bottles 5
5.7 Drying cabinet 5
5.8 Mounting 5
5.9 Cage-stirrer apparatus 6

6 Contamination and decontamination agents 6
6.1 Contaminant solutions 6
6.1.1 Composition of contaminant solutions 6
6.1.2 Preparation of the contaminant solutions 6
6.1.3 Storage of the contaminant solution 7
6.2 Decontamination agents 7

7 Contaminated textile specimen 7
7.1 Reference materials 7
7.2 Number and dimensions of contaminated textile specimens 8

8 Procedure 8
8.1 Determining the specific pulse rate of each contaminant solution 8
8.2 Preparation of the textile specimens 8
8.3 Contamination 9
8.3.1 Preparation 9
8.3.2 Procedure 9
8.4 Decontamination 10
8.4.1 Preparation 10
8.4.2 Procedure 10
8.5 Determining the residual pulse rate, Ir 11

9 Calculation of results and assessment of ease of decontamination 11

10 Test report 12

Annex A (informative) Clamp specimen holder 13

Annex B (normative) Cage-stirrer apparatus for decontamination 14

Annex C (informative) Formulae for the preparation of 60Co and 137Cs or 134Cs contaminant solutions 23

Annex D (informative) Example of a test report 26

Bibliography 28