DIN 51007-1:2024-08 (E)

Thermal analysis (TA) - Differential thermal analysis (DTA) and differential scanning calorimetry (DSC) - Part 1: General Principles

Contents

Page

Foreword 4

1 Scope 6

2 Normative references 6

3 Terms and definitions 6

4 Principle of methods 6
4.1 General 6
4.2 Differential thermal analysis (DTA) and heat-flux differential scanning calorimetry (hf-DSC) 7
4.3 Power compensation differential scanning calorimetry (pc-DSC) 7

5 Apparatus 7
5.1 General 7
5.2 Oven 8
5.3 Temperature control 8
5.4 Apparatus for generating a defined atmosphere 8
5.5 Control, data recording and data evaluation devices 9
5.6 Analytical balance or microbalance 9
5.7 Sample container 9

6 Calibration 9
6.1 General 9
6.2 Calibration substances 10
6.3 Temperature calibration 11
6.4 Heat calibration 12
6.5 Heat capacity calibration 12

7 Objectives of the investigation 14
7.1 Determination of characteristic temperatures and heat of transition 14
7.1.1 First order phase transitions 14
7.1.2 Chemical reactions 18
7.1.3 Glass transition 19
7.2 Determination of heat capacities 23
7.3 Determination of eutectic purity 24
7.4 Other investigation aims 26

8 Sampling 26

9 Sample preparation 27

10 Setting up the apparatus 27

11 Test report 28

Bibliography 30

Figures

Figure 1 — Endothermic peak — Characteristic temperatures or times and types of baseline construction upon heating involving a first order phase transition 16

Figure 2 — Exothermic peak — Characteristic temperatures or times and types of baseline construction upon cooling involving a first order phase transition 17

Figure 3 — Endothermic peak — Construction of a baseline with a point of inflection (option b)..... 18

Figure 4 — Characteristic temperatures and types of baselines for an exothermic peak of a chemical reaction 19

Figure 5 — DSC curve for a sample with glass transition..... 20

Figure 6 — Determination of the glass transition temperature T_g based on the function $H = H(T)$ of a glass transition with enthalpy relaxation..... 21

Figure 7 — Determination of the glass transition temperature based on the heat capacity function $C_p = C_p(T)$ of a glass transition with enthalpy relaxation..... 22

Figure 8 — Determination of the glass transition temperature based on the heat capacity function $C_p = C_p(T)$ of a glass transition without enthalpy relaxation 23

Figure 9 — Determination of heat capacity using two DSC measurements 24

Figure 10 — van't Hoff diagram for determination of eutectic purity (example)..... 26

Tables

Table 1 — Typical temperature ranges 8

Table 2 — Recommended calibration substances 10

Table 3 — Specific heat capacity c_p of synthetic corundum (α-Al_2O_3, "sapphire") [3] [4] 13

Table 4 — Polynomial coefficients for calculating the molar heat capacity of corundum (α-Al_2O_3, "sapphire", molar mass M = 101,961 3 g mol^{-1}) [3] [4]..... 14