DIN EN ISO 9271:2024-10 (E)

Decontamination of radioactively contaminated surfaces - Testing of decontamination agents for textiles (ISO 9271:2023)

Contents

Page

European Foreword ... **3**

Foreword ... **4**

Introduction ... **5**

1 Scope ... **6**

2 Normative references ... **6**

3 Terms, definitions and symbols ... **6**
3.1 Terms and definitions ... 7
3.2 Symbols ... 8

4 Principle ... **8**

5 Apparatus ... **9**
5.1 Beakers ... 9
5.2 Radiation detector ... 9
5.3 Pipettes ... 10
5.4 Two polytetrafluoroethylene (PTFE) or quartz ampoules ... 10
5.5 Thermostat ... 10
5.6 Storage bottles ... 10
5.7 Drying cabinet ... 10
5.8 Mounting ... 10
5.9 Cage-stirrer apparatus ... 11

6 Contamination and decontamination agents ... **11**
6.1 Contaminant solutions ... 11
6.1.1 Composition of contaminant solutions ... 11
6.1.2 Preparation of the contaminant solutions ... 11
6.1.3 Storage of the contaminant solution ... 12
6.2 Decontamination agents ... 12

7 Contaminated textile specimen ... **12**
7.1 Reference materials ... 12
7.2 Number and dimensions of contaminated textile specimens ... 13

8 Procedure ... **13**
8.1 Determining the specific pulse rate of each contaminant solution ... 13
8.2 Preparation of the textile specimens ... 13
8.3 Contamination ... 14
8.3.1 Preparation ... 14
8.3.2 Procedure ... 14
8.4 Decontamination ... 15
8.4.1 Preparation ... 15
8.4.2 Procedure ... 15
8.5 Determining the residual pulse rate, I_r ... 16

9 Calculation of results and assessment of ease of decontamination ... **16**

10 Test report ... **17**

Annex A (informative) **Clamp specimen holder** ... **18**

Annex B (normative) **Cage-stirrer apparatus for decontamination** ... **19**

Annex C (informative) **Formulae for the preparation of ^{60}Co and ^{137}Cs or ^{134}Cs contaminant solutions** ... **28**

Annex D (informative) **Example of a test report** ... **31**

Bibliography ... **33**