DIN EN 15365:2026-02 (E)

Advanced technical ceramics - Mechanical properties of ceramic fibres at high temperature in a non-reactive environment - Determination of creep behaviour by the cold grip method

Contents

Page

European foreword 3

1 Scope 4

2 Normative references 4

3 Terms and definitions 4

4 Principle 7

5 Significance and use 9

6 Apparatus 9
6.1 Test installations 9
6.2 Load train 9
6.3 Test chamber 9
6.4 Set-up for heating 10
6.5 Temperature measurement 10
6.6 Control of deformation 10
6.7 Data recording system 10
6.8 Determination of fibre cross-sectional area 10

7 Test specimens 10
7.1 Test specimen preparation 10
7.2 Number of test specimens 12

8 Test procedures 12
8.1 Determination of the temperature profile in the furnace 12
8.2 Test set-up: Determination of the temperature profile and of the different lengths of each temperature zone in the furnace 12
8.3 Test set-up: Loading considerations 12
8.4 Test technique 12
8.4.1 Specimen mounting 12
8.4.2 Setting of an inert environment 12
8.4.3 Heating of the test specimen 13
8.4.4 Measurements 13
8.4.5 Monitoring of temperature stability 14
8.5 Test validity 14

9 Calculation of results 14
9.1 Creep stress 14
9.2 Creep strain at time t 15
9.2.1 Reading of the longitudinal deformation 15
9.2.2 Calculation of the deformation due to the creep 15
9.2.3 Drawing of the creep curve 15
9.2.4 Creep strain at rupture 15
9.2.5 Creep rupture time 15
9.2.6 Creep strain rate curve 15

10 Test report 16

Bibliography 17