ISO 23971:2025-11 (E)

Surface chemical analysis - X-ray fluorescence analysis of particulate matter filters

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Symbols and abbreviated terms 5

5 Safety 5

6 Preliminary remarks 5

7 Measurements 7

8 Filter materials and interferences 7

9 Sample preparation and handling 7

10 Qualitative Analysis 8
10.1 Identification of analytes 8
10.2 Determination of the analyte net intensities 9
10.3 Determination of LOD 9

11 Quantitative analysis 9
11.1 Certified reference material, reference material and calibration sample 9
11.2 Calibration curve 10
11.3 Uncertainty budget 10
11.4 Precision and accuracy 11

12 Quality check 11

13 Test analysis report 11

Annex A (informative) Contributions to the uncertainty budget 13

Annex B (informative) Calibration procedure 14

Annex C (informative) International interlaboratory comparison 20

Bibliography 27