ISO 11932:2026-10 (E)

Activity measurements of solid materials considered for recycling, re-use or disposal as non-radioactive waste

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Requirements for activity measurements related to generic clearance 3
4.1 General 3
4.2 Surface contamination measurements 4
4.2.1 Radionuclides to be considered 4
4.2.2 Methods to determine surface contamination 4
4.3 Activity concentration measurements 8
4.3.1 General 8
4.3.2 Measurement techniques 8
4.4 Sampling strategy 12

Annex A (informative) Sample decomposition of solid materials for radiochemical analysis 14

Bibliography 17