

ISO 11932:2026-10 (E)

Activity measurements of solid materials considered for recycling, re-use or disposal as non-radioactive waste

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Requirements for activity measurements related to generic clearance	3
4.1 General	3
4.2 Surface contamination measurements	4
4.2.1 Radionuclides to be considered	4
4.2.2 Methods to determine surface contamination	4
4.3 Activity concentration measurements	8
4.3.1 General	8
4.3.2 Measurement techniques	8
4.4 Sampling strategy	12
Annex A (informative) Sample decomposition of solid materials for radiochemical analysis	14
Bibliography	17