ISO 1099:2026-10 (E)

Metallic materials - Fatigue testing - Axial force-controlled method

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Test plan 3

5 Specimen shape and dimensions 4
5.1 Form of specimens 4
5.2 Dimension of specimens 4
5.2.1 Bars and flat sheets > 5 mm thick 4
5.2.2 Flat sheets 5 mm 5

6 Preparation of specimens 6
6.1 General 6
6.2 Machining procedure 6
6.3 Sampling and marking 7
6.3.1 General 7
6.3.2 Surface condition of the specimen 7
6.3.3 Dimensional checks 7
6.3.4 Storage and handling 8

7 Apparatus 8
7.1 Force transducer 8
7.2 Test machine 8
7.3 Alignment check 9

8 Procedure 9
8.1 Gripping of specimen 9
8.2 Mounting of specimen 9
8.3 Selecting testing frequencies 9
8.4 Application of force 10
8.5 Recording of temperature and humidity 10

9 Heating device and temperature measurement 10

10 Instrumentation for test monitoring 10
10.1 Recording systems 10
10.2 Cycle counter 10
10.3 Criterion of failure 10
10.4 Test termination 10

11 Checkingandverification 11

12 Test report 11

Annex A (informative) Presentation of results 18

Bibliography 23