ISO 12800:2003-12 (E)

Nuclear fuel technology - Guide to the measurement of the specific surface area of uranium oxide powders by the BET method

Contents

Page

Foreword iv

1 Scope 1

2 Principle 1
2.1 Summary of the method 1
2.2 Isothermal adsorption curves 1
2.3 Conditions and assumptions 2

3 Procedure 3
3.1 Sample preparation 3
3.2 Volumetric measurement [3, 4] 3
3.3 Gravimetric measurement [5] 3
3.4 Original and single-point methods 3
3.5 Dynamic method (carrier gas method) 4
3.6 Alternative methods 4

4 Expression of results 4
4.1 Methods of calculation 4
4.2 Precision 6

5 Test report 6

Bibliography 7