ISO 21270:2004-06 (E)

Surface chemical analysis - X-ray photoelectron and Auger electron spectrometers - Linearity of intensity scale

---

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative reference 1

3 Symbols 1

4 Outline of the methods 2

5 When to use this International Standard 2

6 Procedure for evaluating the intensity linearity 2
6.1 The samples 2
6.2 Preparing the copper sample 3
6.3 Preparing the stainless-steel sample or sample holder 3
6.4 Choosing the spectrometer settings for which the intensity linearity measurement is required 3
6.5 Operating the instrument 3
6.6 Measurement of the intensity scale linearity by varying the source flux 4
6.7 Determination of the intensity scale linearity by varying the source flux 4
6.8 Measurement of the intensity scale linearity in XPS using the spectrum ratio method for systems with two or more but less than 30 X-ray source emission current settings 6
6.9 Determination of the intensity scale linearity in XPS using the spectrum ratio method for systems with two or more but less than 30 X-ray source emission current settings 7
6.10 Completing the analysis 9

Annex A (informative) Example results of linearity measurements using the spectrum ratio method (the second method) 10

Bibliography 13