ISO 6962:2004-07 (E)

Nuclear energy - Standard method for testing the long-term alpha irradiation stability of matrices for solidification of hi gh-level radioactive waste

Contents

Page

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Principle 2

5 Test Method 2

6 Sample composition 3

7 Sample preparation 3

8 Measurements before storage 3

9 Storage 3

10 Measurements during and after storage 4

11 Test report 5

Bibliography 8