ISO/TS 21432:2005-07 (E)

Non-destructive testing - Standard test method for determining residual stresses by neutron diffraction

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Symbols and abbreviated terms 5
4.1 Symbols 5
4.2 Subscripts 6
4.3 Abbreviated terms 7

5 Summary of method 7
5.1 Preamble 7
5.2 Outline of principle -- Bragg's law 7
5.3 Neutron sources 7
5.4 Strain measurement 7
5.5 Neutron diffractometers 8
5.6 Stress determination 9

6 Preparations for measurements 12
6.1 Preamble 12
6.2 Alignment and calibration of the instrument 12
6.3 Choice of diffraction conditions 12
6.3.1 Monochromatic instruments 12
6.3.2 TOF instruments 15
6.4 Positioning procedures 15
6.5 Gauge volumes 15
6.6 Determination of a strain free or reference lattice spacing 16

7 Material characterization 18
7.1 Preamble 18
7.2 Composition 18
7.3 Thermal/mechanical history 18
7.4 Phases and crystal structures 18
7.5 Homogeneity 18
7.6 Microstructure 18
7.7 Texture 18

8 Recording requirements and measurement procedure 19
8.1 Preamble 19
8.2 Recording requirements 19
8.2.1 General information -- instrument 19
8.2.2 General information -- specimen 20
8.2.3 Specific information required for each strain measurement 20
8.3 Specimen co-ordinates 21
8.4 Positioning of the specimen 21
8.5 Measurement directions 21

8.6 Number and location of measuring positions 21
8.7 Gauge volume 21
8.8 Gauge volume centroid considerations 21
8.9 Temperature 22

9 Calculation of stress 22
9.1 Preamble 22
9.2 Normal stress determinations 22
9.3 Stress state determinations 23
9.3.1 The sin2 method 23
9.4 Choice of elasticity constants 23
9.5 Data analysis 24
9.5.1 Peak fitting function 24
9.5.2 Background function 24
9.5.3 Peak to background ratio 24
9.5.4 Distorted peak profiles 24

10 Reliability of results 25

11 Reporting 25
11.1 Preamble 25
11.2 Strain or stress values 25
11.2.1 Stress free or reference lattice spacing 26
11.2.2 Conversion of strain to stress 26
11.2.3 Elasticity constants 26
11.2.4 Positioning 26
11.3 Neutron source and instrument 26
11.4 General measurement procedures 26
11.5 Specimens/materials properties 26
11.6 Original data 27

Annex A (informative) Measurement procedures 28

Annex B (informative) Determination of uncertainties in a measurand 36

Bibliography 39