ISO 28801:2011-03 (E)

Double sampling plans by attributes with minimal sample sizes, indexed by producer's risk quality (PRQ) and consumer's risk quality (CRQ)

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Terms, definitions, abbreviations and symbols 1

3 Choosing and operating a sampling plan 4

4 Operating characteristics 5

5 Average sample sizes 5

6 Actual producer's and consumer's risks 6

7 Average outgoing quality (AOQ) 6

8 Examples 7

9 Tables and figures 7

Annex A (informative) Statistical theory underlying the plans, tables and figures 63

Bibliography 70