ISO 3951-4:2011-08 (E)

Sampling procedures for inspection by variables - Part 4: Procedures for assessment of declared quality lev els

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 2

3 Terms, definitions, symbols and abbreviations 2

4 Principles 3

5 Declared quality level (DQL) 4

6 Sampling plans 5

7 Operating a sampling plan 8

8 Further information 15

Annex A (informative) Method of matching variables plans to attributes plans 20

Annex B (informative) Examples of use of the procedures 21

Bibliography 25