ISO 11095:1996-02 (E)

Linear calibration using reference materials

Contents

Page

1 Scope 1

2 Normative references 1

3 Definitions 1

4 General principles 2

5 Basic method 2

6 The steps of the basic method 4

7 Control method 10

8 Two alternatives to the basic method 13

9 Example 16

Annexes

A List of symbols and abbreviations 25

B Basic method when the number of replicates is not constant 27

C Bibliography 29