ISO 7870-6:2016-02 (E)

Control charts - Part 6: EWMA control charts

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Symbols and abbreviated terms 1

4 EWMA for inspection by variables 2
4.1 General 2
4.2 Weighted average explained 3
4.3 Control limits for EWMA control chart 4
4.4 Construction of EWMA control chart 4
4.5 Example 6

5 Choice of the control chart 9
5.1 Shewhart control chart versus EWMA control chart 9
5.2 Average run length 10
5.3 Choice of parameters for EWMA control chart 10
5.3.1 Choice of 10
5.3.2 Choice of Lz 11
5.3.3 Calculation for n 11
5.3.4 Example 12

6 Procedure for implementing the EWMA control chart 12

7 Sensitivity of the EWMA to non-normality 13

8 Advantages and limitations 13
8.1 Advantages 13
8.2 Limitations 13

Annex A (informative) Application of the EWMA control chart 14

Annex B (normative) EWMA control chart for controlling a proportion of nonconforming units 18

Annex C (normative) EWMA control charts for a number of nonconformities 20

Annex D (informative) Control chart effectiveness 22

Bibliography 26