ISO 7870-6:2024-07 (E)

Control charts - Part 6: EWMA control charts for the process mean

Contents

Page

Foreword ... **iv**

Introduction ... **v**

1 Scope ... **1**

2 Normative references ... **1**

3 Terms and definitions ... **1**

4 Symbols and abbreviated terms ... **2**

5 EWMA for inspection by variables ... **3**
5.1 General ... 3
5.2 Weighted average explained ... 3
5.3 Control limits for EWMA control chart ... 4
5.4 Construction of EWMA control chart ... 5
5.5 Example ... 7

6 Choice of the control chart ... **10**
6.1 Shewhart control chart versus EWMA control chart ... 10
6.2 Average run length ... 11
6.3 Choice of parameters for EWMA control chart ... 11
6.3.1 Choice of λ ... 11
6.3.2 Choice of L_z ... 12
6.3.3 Calculation for n ... 12
6.3.4 Example ... 13

7 Procedure for implementing the EWMA control chart ... **13**

8 Sensitivity of the EWMA to non-normality ... **14**

9 Advantages and limitations ... **14**
9.1 Advantages ... 14
9.2 Limitations ... 14

Annex A (informative) **Application of the EWMA control chart** ... **16**

Annex B (informative) **EWMA control chart for a proportion of nonconforming items** ... **20**

Annex C (informative) **EWMA control charts for a number of nonconformities** ... **22**

Bibliography ... **24**