# ISO 2859-1:2026-01 (E)

## Sampling procedures for inspection by attributes - Part 1: Sampling schemes indexed by acceptance quality limit (AQL) for lot-by-lot inspection

## Contents

Page


Foreword ..... vi

Introduction ..... vii

1 Scope ..... 1
1.1 Continuous inspection ..... 1
1.2 Skip-lot inspection ..... 2

2 Normative references ..... 2

3 Terms, definitions and symbols ..... 2
3.1 Terms and definitions ..... 2
3.2 Symbols and abbreviations ..... 10

4 Expression of nonconformity ..... 11
4.1 General ..... 11
4.2 Classification of nonconformities ..... 11

5 Acceptance quality limit (AQL) ..... 11
5.1 Use and application ..... 11
5.2 Specifying AQLs ..... 11
5.3 Preferred AQLs ..... 12

6 Submission of product for sampling ..... 12
6.1 Formation of lots ..... 12
6.2 Presentation of lots ..... 12

7 Acceptance and non-acceptance ..... 12
7.1 Acceptability of lots ..... 12
7.2 Disposition of non-acceptable lots ..... 12
7.3 Nonconforming items ..... 12
7.4 Classes of nonconformities or nonconforming items ..... 12
7.5 Special reservation for critical classes of nonconformities ..... 13
7.6 Resubmitted lots ..... 13

8 Drawing of samples ..... 13
8.1 Sample selection ..... 13
8.1.1 General ..... 13
8.1.2 Skip-lot ..... 13
8.2 When to draw the samples ..... 13
8.3 Double or multiple sampling ..... 14

9 Normal, tightened, reduced and skip-lot sampling inspection ..... 14
9.1 Start of inspection ..... 14
9.2 Continuation of inspection ..... 14
9.3 Switching rules and procedures ..... 14
9.3.1 Normal to tightened ..... 14
9.3.2 Tightened to normal ..... 14
9.3.3 Normal to reduced ..... 14
9.3.4 Reduced to normal ..... 16
9.3.5 Skip-lot to normal ..... 16

9.3.6 Reduced to skip-lot ..... 16
9.4 Discontinuation of inspection ..... 16
9.5 Skip-lot sampling inspection ..... 16
9.5.1 General requirements ..... 16
9.5.2 Producer and product qualification ..... 17
9.5.3 Qualification and disqualification ..... 18
9.5.4 Responsibilities on producer qualification ..... 19

10 Sampling plans ..... 19
10.1 Inspection level ..... 19
10.2 Sample size code letters ..... 20
10.3 Obtaining a sampling plan ..... 20
10.4 Types of sampling plans ..... 21

11 Determination of acceptability ..... 21
11.1 Inspection for nonconforming items ..... 21
11.2 Single sampling plans (integer acceptance number) ..... 21
11.3 Double sampling plans ..... 21
11.4 Multiple sampling plans ..... 21
11.5 Inspection for nonconformities ..... 22

12 Further information ..... 22
12.1 Operating characteristic (OC) curves ..... 22
12.2 Process average ..... 22
12.3 Average outgoing quality (AOQ) ..... 22
12.4 Average outgoing quality limit (AOQL) ..... 22
12.5 Average sample size curves ..... 22
12.6 Consumer's and producer's risks ..... 23
12.6.1 Use of individual plans ..... 23
12.6.2 Consumer's risk quality (CRQ) tables ..... 23
12.6.3 Producer's risk (PR) tables ..... 23

13 Fractional acceptance number plans for single sampling (optional) ..... 23
13.1 Application of fractional acceptance number plans ..... 23
13.2 Acceptability determination ..... 24
13.2.1 Inspection for nonconforming items ..... 24
13.2.2 Inspection for number of nonconformities ..... 25
13.3 Switching rules ..... 25
13.3.1 Normal to tightened and tightened to normal ..... 25
13.3.2 Normal to reduced ..... 25
13.3.3 Reduced to normal inspection and discontinuation of inspection ..... 25
13.3.4 Non-constant sampling plan ..... 25

14 Inspection Errors ..... 26

15 Sample size code letters ..... 26

16 Tables of single sampling plans ..... 27

17 Tables of double sampling plans ..... 30

18 Tables of multiple sampling plans ..... 33

19 Tables of producer's risk (PR) ..... 42

20 Tables of consumer risk quality (CRQ) ..... 45

21 Tables of average outgoing quality limits (AOQL) ..... 48

22 Average sample size comparisons by acceptance number ..... 50

23 Tables of single sampling fractional acceptance number plans ..... 52

24 Normalized scheme operating characteristic curves ..... 55

Annex A (informative) Example for non-constant sampling plan ..... 57

Annex B (informative) Sampling strategies ..... 58

Annex C (normative) Procedures for random selection at the skip-lot sampling inspection frequency ..... 60

Annex D (informative) Skip-lot sampling inspection ..... 61

Annex E (informative) The construction of operating characteristic (OC) and average sample number (ASN) curves ..... 66

Annex F (informative) The Construction of Sampling Plans ..... 77

Bibliography ..... 81