ISO 24481-1:2026-08 (E)

Statistical methods for implementation of Six Sigma - Exploratory data analysis - Part 1: General methodology

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Symbols and abbreviated terms 3

5 Fundamental concepts 3
5.1 General 3
5.2 Different types of data sets and possible challenges encountered within EDA 4
5.3 Relation and difference between data visualization (DV) and EDA 5
5.4 Principles and related steps for conducting EDA 5

6 Tools of EDA from different perspectives 6
6.1 General 6
6.2 Certain tools for the different types of data 6
6.2.1 Discrete data 6
6.2.2 Continuous data 7
6.3 Sorted according to their objectives 8
6.4 EDA tools used in each phase of DMAIC 8

7 Emphases and cautions for certain tools and other aspects of EDA 9
7.1 General 9
7.2 Importance of checking the metadata 9
7.3 Cautions about some graphical methods 10
7.3.1 Use graphical methods efficiently 10
7.3.2 Bar charts or dot charts instead of pie charts 11
7.3.3 Avoid misleading graphs and note the data Inking issue 11
7.3.4 Causation is more important than correlation 11
7.3.5 The relationship between EDA and CDA or other tools 12
7.3.6 Choosing suitable data analysis software packages is important for EDA 12

Annex A (informative) Comparison of data visualization and EDA from different aspects 13

Annex B (informative) Some concrete EDA principles in Six Sigma and quality improvement projects 14

Annex C (informative) Limitation of descriptive statistics and a typical example 16

Bibliography 17