ISO 11877:2008-06 (E)

Hardmetals - Determination of silicon in cobalt metal powders - Photometric method

Contents

Page

Foreword iv

1 Scope 1

2 Principle 1

3 Reagents 1

4 Apparatus and equipment 2

5 Preparation of acid mixture for sample treatment 2

6 Preparation of solutions for receiver 2

7 Procedure 2

8 Photometric determination 3

9 Preparation of blank and calibration solutions 3

10 Expression of the result 3

11 Test report 3

Bibliography 4