ISO/ASTM 52933:2024-03 (E)

Additive manufacturing - Environment, health and safety - Test method for the hazardous substances emitted from material extrusion type 3D printers in the non-industrial places

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Hazardous substance targets and major factors 3

5 Relevant test standards 3

6 Sampling conditions 4

6.1 Sampling location 4

6.2 Sampling planning 4

7 Measurement methods 6

7.1 Active and time-integrated methods 6

7.1.1 Purpose 6

7.1.2 VOCs analysis 6

7.1.3 Aldehyde method 9

7.2 Real-time method 11

7.2.1 Purpose 11

7.2.2 Sampling 11

7.2.3 Determination of particles concentration 11

8 Test report 13

Annex A (informative) **Considerations for reducing the emission of hazardous substances** 15

Annex B (informative) **Checklist for reduction of hazardous substances** 22

Bibliography 23