ISO 20947-3:2023-08 (E)

Performance evaluation protocol for digital fitting systems - Part 3: Digital fitting performance - Gap

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Functions 2
4.1 General 2
4.2 Function to measure the perimeter on the virtual cross section 2
4.2.1 Function to measure the perimeter on the virtual horizontal cross section 2
4.2.2 Function to measure the perimeter on the virtual vertical cross section (front centre) 8
4.2.3 Function to measure the perimeter on the virtual vertical cross section (side) 14
4.3 Function to measure the gap on the virtual cross section 20
4.3.1 Function to measure the gap of circumference on the virtual horizontal cross section 20
4.3.2 Function to measure the gap at side on the virtual vertical cross section (front) 27
4.3.3 Function to measure the gap at centre front or centre back on the virtual vertical cross section (side) 32
4.4 Tension map function 38
4.5 Garment pressure display function 41
4.6 Grain display function 44
4.7 Display function for projected cross-sectional garment view 47
4.7.1 General 47
4.7.2 Top 48
4.7.3 Front 50
4.7.4 Side 56

5 Quantitative evaluation of digital fitting performance - Gap based on functions and area measurements 61
5.1 General 61
5.2 Method to measure a physical gap 61

6 Report 66

Annex A (Normative) Format for report: Evaluation of a digital fitting performance 67

Bibliography 68