DIN EN 12131:2026-09 (E)

Feather and down - Test methods - Determination of the quantitative composition of feather and down (manual method)

Contents

Page

European foreword 3

1 Scope 4

2 Normative references 4

3 Terms and definitions 4

4 Principle 4
4.1 General 4

5 Apparatus 4

6 Sampling, conditioning and preparation of the test specimens 5

7 Procedure 5
7.1 General 5
7.2 First separation 5
7.3 Second separation 7
7.4 Milled feathers 8

8 Calculation and expression of results 9
8.1 Calculation of the component portions 9
8.2 Determination of the need for additional testing 11
8.3 Expression of results 11

9 Testing variance 11

10 Test report 11

Bibliography 12