DIN SPEC 4867:2022-04 (E)

Cleaning test methods for the abrasion resistance of glass coatings for solar applications; Text English

Contents

Page

Foreword 4

Introduction 6

1 Scope 7

2 Normative references 7

3 Terms and definitions 7

4 Symbols and abbreviations 8
4.1 Symbols 8
4.2 Abbreviatons 8

5 Apparatus 9
5.1 Test apparatus 9
5.2 Samples 10
5.3 Brushing parameters for coating abrasion resistivity testing (working mode 1) 11
5.4 Auxiliary material and dust-water suspension 12
5.4.1 Working mode 1: coating abrasion resistivity testing 12
5.4.2 Working mode 2: brush and brushing parameter assessment 13
5.5 Reflection measurement equipment 13

6 Test procedure 14
6.1 Preparation of samples and apparatus 14
6.2 Test parameters 14
6.2.1 General 14
6.2.2 Working mode 1: coating abrasion resistivity testing 15
6.2.3 Working mode 2: brush and brushing parameter assessment 15
6.3 Procedures 15
6.3.1 Working mode 1: coating abrasion resistivity testing 15
6.3.2 Working mode 2: brush and brushing parameter assessment 16

7 Measurement 17
7.1 Sampling parameters 17
7.2 Measurement parameters 18

8 Evaluation of the reflectance data 19

9 Test report 20

Annex A (normative) Calibration 22
A.1 Calibration of the washing equipment 22
A.2 Determination of the deposited dust quantity in g/m² 24

Annex B (informative) Example for the integral reflection change 25

Bibliography 26

Figures

Figure 1 — Schematic of test setup 9

Figure 2 — Scheme with reflectance measurements positions for samples with a minimum size of 0,8 m × 1,6 m **17**

Figure 3 — Scheme with reflectance measurement positions for samples with a size < 0,8 m × 1,6 m **18**

Figure A.1 — Schematic top view of the cardboard positioning procedure for the detection of the right side of the spray pattern **23**

Figure A.2 — Example spray pattern and dimensions that shall be achieved during calibration of the washing equipment **23**

Figure B.1 — Median absolute (left) relative (right) integral effective reflectance change value vs. number of brushing strokes **25**

Tables

Table 1 — Symbols **8**

Table 2 — Predefined particle diameter distribution of feldspar test dust for coating abrasion resistivity testing **12**