ISO 23548:2024-09 (E)

Measurement of radioactivity - Alpha emitting radionuclides - Generic test method using alpha spectrometry

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 2

4 Symbols and units 3

5 Principle 4

6 Chemical reagents and equipment 5
6.1 General 5
6.2 Chemical reagents 5
6.2.1 Water quality 5
6.2.2 Tracer solution 5
6.3 Equipment 6

7 Sampling and samples 9

8 Procedure 9
8.1 General 9
8.2 Calcination 10
8.3 Sample dissolution processes 10
8.4 Specific radiochemical separation procedures 11
8.5 Methods of deposition 12
8.5.1 Direct deposition 12
8.5.2 Spontaneous deposition of polonium 12
8.5.3 Microprecipitation 13
8.5.4 Electrodeposition 13
8.6 Measurement 14
8.6.1 Measurement geometry 14
8.6.2 Spectrum exploitation 14
8.6.3 Energy calibration 15
8.6.4 Efficiency calibration 16
8.6.5 Global background 17
8.6.6 Chemical yield and total efficiency 17
8.6.7 Quality control sources 18
8.7 Recommended nuclear decay data 18

9 Expression of results 19
9.1 Calculation of activity 19
9.1.1 General 19
9.1.2 Alpha activity 19
9.1.3 Uncertainty 19
9.1.4 Decision threshold 20
9.1.5 Detection limit 20
9.2 Calculation of sample activity 21

9.2.1 General 21
9.2.2 Calculation of derived alpha activity 21
9.2.3 Relative uncertainty 21
9.2.4 Decision threshold 21
9.2.5 Detection limit 22
9.2.6 Coverage interval limits 22

10 Test report 23

Annex A (informative) Generic alpha test method processes 24

Annex B (informative)Examplesofmeltingflux 25

Annex C (informative) Preparation of the source by coprecipitation 26

Annex D (informative) Preparation of the source by electrodeposition 30

Annex E (informative) Alpha peak integration with minimized uncertainty 33

Bibliography 35