ISO 25337:2010-03 (E)

Plastics - Production quality control - Statistical method for using single measurements

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Precision of test methods 2

5 Single measurements for production quality control purposes 3
5.1 General 3
5.2 Variability of the production process and test method 3
5.3 Within-laboratory reproducibility 4
5.4 Calculation of sRLab from a within-laboratory reproducibility investigation 4
5.5 Interpretation of single-measurement data for production quality control purposes 5

6 Procedure 8

Annex A (informative) Example of the calculation of sRlab from a within-laboratory reproducibility investigation 9

Annex B (informative) Examples of the effect on production limits of making duplicate and triplicate measurements as opposed to single measurements 11

Annex C (normative) Reducing the probability of incorrectly accepting a nonconforming product ... 15

Bibliography 17