ISO 4892-2:2013-03 (E)

Plastics - Methods of exposure to laboratory light sources - Part 2: Xenon-arc lamps

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Principle 1

4 Apparatus 2
4.1 Laboratory light source 2
4.2 Test chamber 4
4.3 Radiometer 5
4.4 Black-standard/black-panel thermometer 5
4.5 Wetting and humidity-control equipment 5
4.6 Specimen holders 5
4.7 Apparatus to assess changes in properties 6

5 Test specimens 6

6 Exposure conditions 6
6.1 Radiation 6
6.2 Temperature 6
6.3 Relative humidity of chamber air 7
6.4 Spray cycle 7
6.5 Cycles with dark periods 8
6.6 Sets of exposure conditions 8

7 Procedure 9
7.1 General 9
7.2 Mounting the test specimens 9
7.3 Exposure 9
7.4 Measurement of radiant exposure 9
7.5 Determination of changes in properties after exposure 9

8 Exposure report 9

Annex A (informative) Filtered xenon-arc radiation -- Relative spectral irradiance 10

Annex B (normative) Additional exposure cycles 11

Bibliography 13