DIN EN 13999-1:2014-03 (E)

Adhesives - Short term method for measuring the emission properties of low-solvent or solv ent-free adhesives after application - Part 1: General procedure

Contents

Page

Foreword 3

Introduction 5

1 Scope 6

2 Normative references 6

3 Terms and definitions 6

4 Principle 6

5 Apparatus 7
5.1 General 7
5.2 Support 7
5.3 Adhesive coating device 7
5.4 Emission test chamber 7
5.5 Air supply and mixing facilities 8
5.6 Air sampling devices 9
5.7 Devices for desorption and analysis 9

6 Adhesive sample 9
6.1 General 9
6.2 Pre-conditioning 9
6.3 Preparation of a test specimen 9

7 Procedure 10
7.1 Number of determinations 10
7.2 Preconditioning of the test chamber 10
7.3 Operation of the test chamber 10
7.4 Starting of the test 10
7.5 Sampling and analysis of emitted substances 10

8 Expression of results 11
8.1 Calculations 11
8.2 Carcinogenic and sensitizing compounds concentration 11
8.3 Volatile organic compounds 11
8.3.1 General 11
8.3.2 Determination of the specific emission rate at the sampling times 11
8.3.3 Determination of the empirical parameters a and b 12

9 Test report 13

Annex A (normative) Carcinogenic and sensitizing substances 14

Bibliography 15