ISO 11357-1:2016-09 (E)

Plastics - Differential scanning calorimetry (DSC) - Part 1: General principles

Contents

Page

Foreword v

Introduction vi

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Basic principles 8
4.1 General 8
4.2 Heat-flux DSC 8
4.3 Power-compensation DSC 8

5 Apparatus and materials 9

6 Specimen 10

7 Test conditions and specimen conditioning 11
7.1 Test conditions 11
7.2 Conditioning of specimens 11

8 Calibration 11
8.1 General 11
8.2 Calibration materials 12
8.3 Temperature calibration 12
8.3.1 General 12
8.3.2 Procedure 12
8.3.3 Accuracy of calibration 13
8.4 Heat calibration 13
8.4.1 General 13
8.4.2 Procedure 14
8.4.3 Accuracy of calibration 14
8.5 Heat flow rate calibration 15
8.5.1 General 15
8.5.2 Procedure 15

9 Procedure 17
9.1 Setting up the apparatus 17
9.1.1 Switching on 17
9.1.2 Purge gas 17
9.1.3 Experimental conditions 17
9.1.4 Baseline determination 17
9.2 Loading the specimen into the crucible 17
9.2.1 General 17
9.2.2 Selection of crucibles 18
9.2.3 Weighing the specimen crucible 18
9.2.4 Loading the specimen 18
9.2.5 Determination of the mass of the specimen 18
9.3 Insertion of crucibles into the instrument 18
9.4 Performing measurements 18

9.4.1 General 18
9.4.2 Scanning mode 18
9.4.3 Isothermal mode 19
9.5 Post-run checks 20
9.5.1 Check for loss in mass 20
9.5.2 Inspection of specimens 20
9.5.3 Checking of crucibles and crucible holder 20

10 Test report 20

Annex A (normative) Extended, high-precision, temperature calibration[12] 22

Annex B (normative) Extended, high-precision, heat calibration 24

Annex C (informative) Recommended calibration materials 26

Annex D (informative) Interaction of calibration materials with different crucible materials 29

Annex E (informative) General recommendations 31

Bibliography 33