ISO 11357-2:2020-03 (E)

Plastics - Differential scanning calorimetry (DSC) - Part 2: Determination of glass transition temperature and step height

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Principle 1

5 Apparatus and materials 2

6 Test specimens 2

7 Test conditions and specimen conditioning 2

8 Calibration 2

9 Procedure 2
9.1 Setting up the apparatus 2
9.2 Loading the test specimen into the crucible 2
9.3 Insertion of crucibles 2
9.4 Temperature scan 2

10 Expression of results 3
10.1 Determination of glass transition temperatures 3
10.1.1 General 3
10.1.2 Equal-areas method 4
10.1.3 Half-step-height method 6
10.1.4 Inflection-point method 7
10.2 Determination of glass transition step height 8

11 Precision 8

12 Test report 8

Bibliography 9