ISO 2114:2000-08 (E)

Plastics (polyester resins) and paints and varnishes (binders) - Determination of partial acid value and total acid value

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Principle 2

5 Reagents 2

6 Apparatus 3

7 Procedure 4

8 Calculation and expression of results 6

9 Precision 7

10 Test report 8

Annex A (informative) Checking the concentration of the standard potassium hydroxide solution 9