ISO 4892-4:2024-12 (E)

Plastics - Methods of exposure to laboratory light sources - Part 4: Open-flame carbon-arc lamps

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms and definitions 1

4 Principle 1

5 Apparatus 2
5.1 Laboratory light source 2
5.1.1 General 2
5.1.2 Spectral irradiance of open-flame carbon-arc lamps with daylight filters (type 1) 2
5.1.3 Spectral irradiance of open-flame carbon-arc lamps with window-glass filters (type 2) 3
5.1.4 Spectral irradiance of open-flame carbon-arc lamps with extended-UV filters (type 3) 4
5.1.5 Typical spectral irradiance: 4
5.1.6 Factors that can affect the spectral power distribution of open-flame carbon- arc lamps 6
5.2 Test chamber 7
5.3 Radiometer 7
5.4 Thermometer 7
5.5 Moisture 7
5.5.1 General 7
5.5.2 Relative-humidity control equipment 7
5.5.3 Spray system 7
5.6 Specimen holders 7
5.7 Apparatus to assess changes in properties 8

6 Test specimens 8

7 Test conditions 8
7.1 Temperature 8
7.1.1 Black-standard/black-panel temperature 8
7.1.2 Chamber air temperature 8
7.2 Relative humidity of air 8
7.3 Spray cycle 8
7.4 Cycles with dark periods 9

8 Procedure 9
8.1 Mounting the test specimens 9
8.2 Exposure 9
8.3 Measurement of radiant exposure 9
8.4 Determination of changes in properties after exposure 9

9 Exposure report 9

Bibliography 10