ISO 877-3:2026-05 (E)

Plastics - Methods of exposure to solar radiation - Part 3: Intensified weathering using concentrated solar radiation

Contents

Page

Foreword ... **iv**

1 Scope ... **1**

2 Normative references ... **1**

3 Terms and definitions ... **1**

4 Principle ... **1**

5 Apparatus ... **2**
5.1 General requirements ... 2
5.2 Apparatus for measurement of climatic factors ... 3

6 Test specimens ... **3**

7 Exposure conditions ... **4**
7.1 Orientation of mirrors ... 4
7.2 Exposure site ... 4
7.3 Temperature control ... 4
7.4 Irradiance level ... 5

8 Exposure stages ... **6**
8.1 General ... 6
8.2 Solar radiant exposure ... 6
8.2.1 Guidance for selection of the exposure stage ... 6
8.2.2 Instrumental measurement of solar radiant exposure ... 6

9 Procedure ... **7**
9.1 Mounting of test specimens ... 7
9.2 Mounting of reference materials (if used) ... 7
9.3 Climatic observations ... 7
9.4 Exposure of test specimens ... 7
9.4.1 General ... 7
9.4.2 Exposure cycles ... 7
9.4.3 Testing under glass ... 7

10 Expression of results ... **8**
10.1 Determination of changes in properties ... 8
10.2 Climatic conditions and observations ... 8
10.2.1 General ... 8
10.2.2 Temperature ... 8
10.2.3 Relative humidity ... 8
10.2.4 Levels (values) of exposure stages ... 8
10.2.5 Radiation measurement ... 9
10.2.6 Precipitation ... 9
10.2.7 Time of wetness ... 9
10.2.8 Other observations ... 9

11 Test report ... **9**

Bibliography ... **10**