ISO 1183-1:2004-02 (E)

Plastics - Methods for determining the density of non-cellular plastics - Part 1: Immersion met hod, liquid pyknometer method and titration method

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Conditioning 2

5 Methods 3
5.1 Method A -- Immersion method 3
5.2 Method B -- Liquid pyknometer method 5
5.3 Method C -- Titration method 6

6 Correction for buoyancy in air 7

7 Test report 8

Annex A (informative) Liquid systems suitable for use in Method C 9