ISO 11402:2004-03 (E)

Phenolic, amino and condensation resins - Determination of free-formaldehyde content

Contents

Page

Foreword iv

1 Scope 1

2 Normative references 1

3 Terms and definitions 2

4 Test procedures 2
4.1 General 2
4.2 Hydroxylamine hydrochloride procedure 2
4.3 Sulfite procedure 4
4.4 KCN procedure 7

5 Test report 10

Annex A (informative) Suitability of the procedures for different types of resin 11

Annex B (informative) Removal of Hg^{2+} and CN^- from mercury and cyanide residues 12