DIN EN 15023-3:2010-12 (E)

Copper and copper alloys - Determination of nickel content - Part 3: Flame atomic absorption spectrometric method (FAAS)

Contents

Page

Foreword 3

1 Scope 4

2 Normative references 4

3 Principle 4

4 Reagents 4

5 Apparatus 5

6 Sampling 5

7 Procedure 5
7.1 Preparation of the test portion solution 5
7.1.1 General 5
7.1.2 Nickel mass fractions between 0,001 % and 0,012 5 % 6
7.1.3 Nickel mass fractions between 0,01 % and 0,25 % 6
7.1.4 Nickel mass fractions between 0,2 % and 6,0 % 6
7.2 Blank test 6
7.3 Check test 6
7.4 Establishment of the calibration curve 7
7.4.1 Preparation of the calibration solutions 7
7.4.2 Adjustment of the atomic absorption spectrometer 9
7.4.3 Spectrometric measurement of the calibration solutions 9
7.4.4 Calibration curve 9
7.5 Determination 9
7.5.1 General 9
7.5.2 Preliminary spectrometric measurement 9
7.5.3 Spectrometric measurements 9

8 Expression of results 10
8.1 Use of calibration curve 10
8.2 Use of bracketing method 10

9 Precision 11

10 Test report 12

Bibliography 13