DIN EN 15916-2:2010-12 (E)

Copper and copper alloys - Determination of tellurium content - Part 2: Medium tellurium content - Flame atomic ab sorption spectrometric method (FAAS)

Contents

Page

Foreword 3

1 Scope 4

2 Normative references 4

3 Principle 4

4 Reagents 4

5 Apparatus 5

6 Sampling 5

7 Procedure 5
7.1 Preparation of the test portion solution 5
7.2 Blank test 5
7.3 Check test 5
7.4 Establishment of the calibration curve 6
7.5 Determination 7

8 Expression of results 7
8.1 Use of calibration curve 7
8.2 Use of bracketing method 8

9 Precision 8

10 Test report 9

Bibliography 10