ISO 24181-1:2024-08 (E)

Rare earth - Determination of non-rare earth impurities in individual rare earth metals and their oxides - I CP-AES - Part 1: Analysis of Al, Ca, Mg, Fe and Si

Contents

Page

Foreword iv

Introduction v

1 Scope 1

2 Normative references 1

3 Termsanddefinitions 1

4 Principle 3

5 Reagent 4

6 Apparatus 4
6.1 Volumetric glassware 4
6.2 Inductively coupled plasma atomic emission spectrometer 4
6.2.1 General 4
6.2.2 Line spectra selection 4

7 Procedure 5
7.1 Weighing the test portion 5
7.2 Sample preparation 6
7.3 Preparation of calibration solutions 6
7.4 Measurements 7
7.4.1 Instrument set-up 7
7.4.2 Measurement of the calibration solution and calibration curve construction 7
7.4.3 Measurement of the test solution 7

8 Calculation and expression of results 7
8.1 Method of calculation 7
8.2 Precision 8
8.2.1 Interlaboratory test 8
8.2.2 Statistical analysis 8

9 Test report 8

Annex A (informative) Interlaboratory test results 9

Annex B (informative) Regression formulae of precision 10

Bibliography 11