# DIN EN 15022-3:2006-12 (E)

## Copper and copper alloys - Determination of tin content - Part 3: Low tin content - Flame atomic absorption spectromet ry method (FAAS)

## Contents

Page


Foreword ..... 3

1 Scope ..... 4

2 Normative references ..... 4

3 Principle ..... 4

4 Reagents and materials ..... 4

5 Apparatus ..... 5

6 Sampling ..... 5

7 Procedure ..... 6

8 Expression of results ..... 8

9 Precision ..... 9

10 Test report ..... 10

Bibliography ..... 11