DIN EN 15063-2:2007-01 (E)

Copper and copper alloys - Determination of main constituents and impurities by wavelength di spersive X-ray fluorescence spectrometry (XRF) - Part 2: Routine method

Contents

Page

Foreword 3

1 Scope 4

2 Normative references 4

3 Principle 4

4 Terms and definitions 4

5 Apparatus 4

6 Sampling 6

7 Procedure 6

8 Expression of results 8

9 Precision 8

10 Test report 8

Annex A (informative) Conditions for the analysis 9

Bibliography 10