DIN EN 16729-5:2023-07 (E)

Railway applications - Infrastructure - Non-destructive testing on rails in track - Part 5: Non-destructive testing on welds in track

Contents

Page

European foreword 4

Introduction 5

1 Scope 6

2 Normative references 6

3 Terms and definitions 6

4 Symbols and abbreviations 6

5 NDT methods to detect defects in rail welds 7
5.1 General 7
5.2 Visual testing - VT 9
5.2.1 General 9
5.2.2 VT inspection zone 9
5.2.3 Example of defects 9
5.3 Ultrasonic Testing -- UT 9
5.3.1 General 9
5.3.2 UT inspection zone 9
5.3.3 Example of defects 9

6 Description of weld defects 10
6.1 Defects in electric arc repair welds 10
6.1.1 Volumetric defects - Porosity 10
6.1.2 Planar defects 11
6.2 Defects in flash butt welds (Tri-metallic welds) 15
6.3 Defects in aluminothermic weld 17
6.3.1 Volumetric defects 17
6.3.2 Planar defects 23
6.3.3 Thermal contraction (Hot Tear) 27
6.3.4 Fatigue cracks 28

7 Documentation 30
7.1 General 30
7.2 Requirements of documentation VT 30
7.3 Requirements of documentation UT 30

Annex A (informative) Visual testing procedures on welds 31

A.1 General 31
A.2 Visual testing on welds 31
A.2.1 Testing equipment 31
A.2.2 Testing preparation and procedure 31

Annex B (informative) Ultrasonic testing procedures on welds 32

B.1 General 32
B.2 Ultrasonic testing on welds 32
B.2.1 Testing equipment 32

B.2.2 Testing preparation and procedures 39
B.3 Phase W: Walking stick 39
B.3.1 General 39
B.3.2 Overview 39
B.3.3 Reference block for inspection W.1 39
B.3.4 Reference block for inspections W.2 and W.3 39
B.3.5 Transfer correction applied to inspections W.1 to W.3 40
B.3.6 Couplant 40
B.3.7 Inspection zone 40
B.4 Phase H: Single probes 40
B.4.1 General 40
B.4.2 Overview 40
B.4.3 Reference block for inspection H.1 40
B.4.4 Reference block for inspection H.2 41
B.4.5 Reference block for inspections H.3 and H.4 41
B.4.6 Transfer correction applied to inspections H.1 to H.4 41
B.4.7 Couplant 44
B.4.8 Inspection zones 44
B.5 Phase T: Tandem 45° on the running surface 48
B.5.1 Overview 48
B.5.2 Reference block for inspection T.1 48
B.5.3 Transfer correction applied to inspection T.1 48
B.5.4 Couplant 48
B.5.5 Inspection zone for T.1 48
B.6 Phase TS: Tandem 70° on the side of the rail head, web and foot 49
B.6.1 Overview 49
B.6.2 Reference block for inspection TS.1 50
B.6.3 Reference block for inspection TS.2 51
B.6.4 Reference block for inspection TS.3 52
B.6.5 Transfer correction applied to inspections TS.1 to TS.3 52
B.6.6 Couplant 53
B.6.7 Inspection zones 53

Bibliography 55