ISO/TS 13399-304:2016-02 (E)

Cutting tool data representation and exchange - Part 304: Creation and exchange of 3D models - Solid milling cutters with arbor hole

Contents

Page

Foreword v

Introduction vii

1 Scope 1

2 Normative references 1

3 Starting elements, coordinate systems, planes 2
3.1 General 2
3.2 Reference system 2
3.3 Coordinate system at the cutting part 3
3.4 Planes 3
3.5 Cutting reference point (CRP) 4

4 Design of the model 5
4.1 Necessary properties for the connection interface feature 5

5 Plain milling cutter 6
5.1 General 6
5.2 Necessary properties 6
5.3 Geometry of the non-cutting part inclusive of the connection 7
5.4 Geometry of the cutting part 9
5.5 Plain milling cutter, complete 9

6 Shell mill 9
6.1 General 9
6.2 Necessary properties 10
6.3 Geometry of the non-cutting part inclusive of the connection 10
6.4 Geometry of the cutting part 10
6.5 Shell mill, complete 10

7 Thread milling cutter 11
7.1 General 11
7.2 Necessary properties 11
7.3 Geometry of the non-cutting part inclusive of the connection 12
7.4 Geometry of the cutting part 12
7.5 Thread milling cutter, complete 12

8 Slotting cutter 12
8.1 General 12
8.2 Necessary properties 13
8.3 Geometry of the non-cutting part inclusive of the connection 13
8.4 Geometry of the cutting part 13
8.5 Slotting cutter, complete 14

9 Pointedprofileslottingcutter 14
9.1 General 14
9.2 Necessary properties 15
9.3 Geometry of the non-cutting part inclusive of the connection 15
9.4 Geometry of the cutting part 16

9.5 Pointed profile slotting cutter 16

10 Flattedprofileslottingcutter 16
10.1 General 16
10.2 Necessary properties 17
10.3 Geometry of the non-cutting part inclusive of the connection 18
10.4 Geometry of the cutting part 18
10.5 Flatted profile slotting cutter, complete 18

11 Concaveprofilecutter 18
11.1 General 18

11.2 Necessary properties 19
11.3 Geometry of the non-cutting part inclusive of the connection 19
11.4 Geometry of the cutting part 20
11.5 Concave profile cutter, complete 20

12 Convexprofilecutter 20
12.1 General 20
12.2 Necessary properties 21
12.3 Geometry of the non-cutting part inclusive of the connection 21
12.4 Geometry of the cutting part 21
12.5 Convex profile cutter, complete 21

13 Corner-rounding cutter 22
13.1 General 22
13.2 Necessary properties 23
13.3 Geometry of the non-cutting part inclusive of the connection 23
13.4 Geometry of the cutting part 23
13.5 Corner-rounding cutter, complete 23

14 Angular milling cutter 24
14.1 General 24
14.2 Necessary properties 24
14.3 Geometry of the non-cutting part inclusive of the connection 25
14.4 Geometry of the cutting part 25
14.5 Angular milling cutter, complete 25

15 Angularprofilemillingcutter 26
15.1 General 26
15.2 Necessary properties 26
15.3 Geometry of the non-cutting part inclusive of the connection 27
15.4 Geometry of the cutting part 27
15.5 Angular profile milling cutter, complete 27

16 Sawing blade 27
16.1 General 27
16.2 Necessary properties 28
16.3 Geometry of the non-cutting part inclusive of the connection 28
16.4 Geometry of the cutting part 28
16.5 Sawing blade, complete 28

17 Design of details 29
17.1 Basics for modelling 29
17.2 Contact surfaces, driving features -- Orientation 29

18 Attributes of surfaces -- Visualization of the model features 29

19 Structure of the design elements (tree of model) 29

20 Data exchange model 30

Annex A (informative) Information about nominal dimensions 32

Bibliography 33