ISO/TS 13399-309:2016-03 (E)

Cutting tool data representation and exchange - Part 309: Creation and exchange of 3D models - Tool holders for indexable inserts

Contents

Page

Foreword vi

Introduction viii

1 Scope 1

2 Normative references 1

3 Starting elements, coordinate systems, planes 2
3.1 General 2
3.2 Reference system (PCS -- primary coordinate system) 2
3.3 Tool item position 2
3.3.1 Prismatic tool position 3
3.3.2 Round tool position 3
3.4 Planes 4
3.5 Cutting reference point (CRP) 5
3.6 Design of the pocket seat 8
3.7 Adjustment coordinate system on workpiece side 12
3.7.1 General 12
3.7.2 Designation of the coordinate system workpiece side 12

4 Design of the model 14
4.1 Necessary parameters for the connection interface feature 14
4.2 Necessary properties for insert and pocket seat 15
4.2.1 General 15
4.2.2 Properties for equilateral, equiangular and equilateral, non- equiangular inserts 15
4.2.3 Properties for non-equilateral, equiangular and non-equilateral, non- equiangular inserts 15
4.2.4 Properties for round inserts 16
4.2.5 Design of the pocket seat feature 16

5 Tool holder for longitudinal and transversal turning 17
5.1 General 17
5.2 Necessary properties 17
5.3 Basic geometry 18
5.4 Turning tool with pocket seat and top surface offset 21
5.5 Turning tool assembly 21
5.6 Boring bar body 22

6 Turning tool for external threading 24
6.1 General 24
6.2 Necessary properties 24
6.3 Basic geometry 25
6.4 Turning tool with pocket seat and top surface offset 25
6.5 Turning tool assembly 26

7 Boring bar for internal threading 27
7.1 General 27
7.2 Necessary properties 27
7.3 Basic geometry 28
7.4 Boring bar with pocket seat and top surface offset 29
7.5 Boring bar assembly 30

8 Turning tool for OD grooving and parting 30
8.1 General 30
8.2 Necessary properties 30
8.3 Basic geometry 32
8.4 Grooving tool with pocket seat and top surface offset 33
8.5 Grooving and cut-off tool assembly 33

9 Boring bar for ID grooving 34
9.1 General 34
9.2 Necessary properties 34
9.3 Basic geometry 35
9.4 Boring bar with pocket seat and top surfaces 36
9.5 Grooving boring bar assembly 37

10 Pull back boring bar 37
10.1 General 37
10.2 Necessary properties 38
10.3 Basic geometry 38
10.4 Boring bar with pocket seat and top surfaces 39
10.5 Pull back boring bar assembly 39

11 System tool for external turning 40
11.1 General 40
11.2 Necessary properties 40
11.3 Basic geometry 41
11.4 System tool with pocket seat and top surfaces 41
11.5 Assembly of system tool for external turning 42

12 System tool for external threading 43
12.1 General 43
12.2 Necessary properties 43
12.3 Basic geometry 44
12.4 System tool with pocket seat and top surfaces 44
12.5 Assembly of a system tool for external threading 44

13 System tool for internal turning 44
13.1 General 44
13.2 Necessary properties 45
13.3 Basic geometry 45
13.4 System tool with pocket seat and top surfaces 45
13.5 System tool for internal turning assembly 45

14 System tool for internal threading 46
14.1 General 46
14.2 Necessary properties 46
14.3 Basic geometry 46
14.4 System tool with pocket seat and top surfaces 46
14.5 System tool for internal threading assembly 46

15 System tool for OD grooving and/or cut-off 47
15.1 General 47
15.2 Necessary properties 47
15.3 Basic geometry 48
15.4 Grooving tool with pocket seat and top surface offset 48
15.5 System tool for OD grooving and parting assembly 48

16 System tool for ID grooving 49
16.1 General 49
16.2 Necessary properties 49
16.3 Basic geometry 49

16.4 Grooving tool with pocket seat and top surface offset 49
16.5 System tool for ID grooving assembly 49

17 Pull back system tool 50
17.1 General 50
17.2 Necessary properties 50
17.3 Basic geometry 50
17.4 System tool with pocket seat and top surfaces 51
17.5 Pull back system tool assembly 51

18 System tool, neutral design for OD turning 51
18.1 General 51
18.2 Necessary properties 51
18.3 Basic geometry 52
18.4 System tool with pocket seat and top surfaces 52
18.5 System tool, neutral design for OD turning assembly 52

19 Design of details 52
19.1 Basics for modelling 52
19.2 Fixing threads for inserts 52
19.3 Contact surfaces/drive keys -- Orientation 52
19.4 Chamfers and roundings 52

20 Attributes of surfaces -- Visualization of the model features 52

21 Structure of the design elements (tree of model) 53

22 Data exchange model 54

Annex A (normative) Mirror planes for left-handed tools 56

Annex B (informative) Information about nominal dimensions 57

Bibliography 58