

ISO/TS 13399-310:2017-02 (E)

Cutting tool data representation and exchange - Part 310: Creation and exchange of 3D models - Turning tools with carbide tips

Contents

Page

Foreword	v
Introduction	vi
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Starting elements, coordinate systems, planes	2
4.1 General	2
4.2 Reference system (PCS -- primary coordinate system)	2
4.3 Tool item position	3
4.3.1 General	3
4.3.2 Prismatic tool position	3
4.3.3 Round tool position	3
4.4 Planes	4
4.5 Cutting reference point	5
4.6 Design of the pocket of the tip	6
4.6.1 General	6
4.6.2 Design of the body of the tip	6
4.7 Adjustment coordinate system on workpiece side	9
4.7.1 General	9
4.7.2 Designation of the coordinate system workpiece side	9
5 Design of the model	11
5.1 General	11
5.2 Necessary parameters for the connection interface feature	12
6 Turning tool No. 1 -- Straight design	12
6.1 General	12
6.2 Necessary properties	12
6.3 Basic geometry	13
6.4 Turning tool No. 1 -- Solid body	14
7 Turning tool No. 2 -- Bent design	14
7.1 General	14
7.2 Necessary properties	14
7.3 Basic geometry	14
7.4 Turning tool No. 2 -- Solid body	15
8 Turning tool No. 3 and 6 -- Offset side cutting design	15
8.1 General	15
8.2 Necessary properties	16
8.3 Basic geometry	17
8.4 Turning tool No. 3 and 6 -- Solid body	17
9 Turning tool No. 4 -- Straight grooving design	17
9.1 General	17
9.2 Necessary properties	18

9.3	Basic geometry	18
9.4	Turning tool No. 4 -- solid body	19
10	Turning tool No. 5 -- Offset end cutting design	19
10.1	General	19
10.2	Necessary properties	20
10.3	Basic geometry	20
10.4	Turning tool No. 5 -- Solid body	20
11	Turning tool No. 7 -- Grooving and cut-off design	21
11.1	General	21
11.2	Necessary properties	21
11.3	Basic geometry	21
11.4	Turning tool No. 7 -- Solid body	22
12	Turning tool -- Pointed straight design	22
12.1	General	22
12.2	Necessary properties	23
12.3	Basic geometry	23
12.4	Turning tool -- Solid body	23
13	Internal turning tool No. 8 -- Offset end cutting design	24
13.1	General	24
13.2	Necessary properties	24
13.3	Basic geometry	25
13.4	Complete internal offset end cutting turning tool	25
14	Internal turning tool No. 9 -- Offset side cutting design	26
14.1	General	26
14.2	Necessary properties	26
14.3	Basic geometry	27
14.4	Complete internal offset side cutting turning tool	27
15	Design of details	27
15.1	Basics for modelling	27
15.2	Contact surfaces/location flats -- Orientation	27
15.3	Chamfers, rounding, others	27
16	Attributes of surfaces -- Visualization of the model features	27
17	Data exchange model	28
Annex A (normative) Mirror plane for left-handed tools		32
Annex B (informative) Information about nominal dimensions		33
Bibliography		34