ISO 6789-1:2017-02 (E)

Assembly tools for screws and nuts - Hand torque tools - Part 1: Requirements and method s for design conformance testing and quality conformance testing: minimum requirements for declaration of conformance

Contents

Page

Foreword iv

Introduction vi

1 Scope 1

2 Normative references 1

3 Terms,definitionsandsymbols 1
3.1 Terms and definitions 1
3.2 Symbols, designations and units 3

4 Classification 3

5 Requirements 3
5.1 Design conformance testing 3
5.1.1 General 3
5.1.2 Maximum torque values 4
5.1.3 Specified torque range 4
5.1.4 Scales, dials and displays 4
5.1.5 Maximum permissible deviation 5
5.1.6 Overloading test 5
5.1.7 Endurance test 5
5.1.8 Effect of geometric changes 6
5.2 Quality conformance testing 7
5.3 Conformance test during use 7

6 Torque measurement 7
6.1 Torque measurement system 7
6.2 Application of torque 8
6.3 Ambient conditions 8
6.4 Measurement requirements 9
6.5 Measurement sequence 11
6.5.1 General 11
6.5.2 Indicating torque tools, Type I 11
6.5.3 Setting torque tools, Type II 11

7 Calculation of deviation 12
7.1 General 12
7.2 Calculation example 1 12
7.3 Calculation example 2 13

8 Declaration of conformance 14

9 Marking 15

Annex A (normative) Examples of indicating torque tools (Type I) 16

Annex B (normative) Examples of setting torque tools (Type II) 17

Annex C (informative)Measurementsequenceflowchartfortorquetools 19

Bibliography 22