DIN EN 15446:2008-04 (E)

Fugitive and diffuse emissions of common concern to industry sectors - Measurement of fugitive emission of vapours generating from equipment and piping leaks

Contents

Page

Foreword 3

Introduction 4

1 Scope 5

2 Normative references 5

3 Terms and definitions 5

4 Measurement equipment 6

5 Chemicals / Calibration gases 7

6 Procedures 8

7 Precision 11

8 Report 12

Bibliography 17

Annex C (normative) Correlation between screening values and emission rates 15

Annex A (normative) Evaluation procedure of instrument performance parameters 13

Annex B (normative) Calculation of response factor for mixtures 14